



Surface Designs  
Triple R Specialty Coatings  
38 Scott Street West  
St Catharines, ON  
L2R 1C9

Rick Cuthbert

Reference Letter regarding: Floor Sealant

For several years we have experienced problems with the floor covering in the After Hours SAC building. The rubber flooring was delaminating and causing safety problems by the blistering or bubbling of the floor covering in various spots.

Upon investigation it was found that moisture was causing the sealant between the flooring material and concrete to break down due to excessive moisture content. We contracted Triple R Specialty Coatings to apply the Koster Vap 1 2000 moisture emission system to the floor before we recovered it with a new flooring material.

This work was carried out in the summer of 2004 and to date there has been no evidence that a moisture issue exists or is the cause of any floor covering material failure.

During the installation of this material Triple R Specialty Coating acted in a professional manner during the testing, application and commissioning of the new flooring system.

Thank you

**Bart  
Lanni**

Digitally signed by Bart Lanni  
DN: cn=Bart Lanni, o=CA,  
o=Niagara College, ou=FMS,  
email=blanni@niagara.on.ca  
Reason: I am the author of this  
document  
Date: 2005.03.23 22:17:45 -0500

Bart Lanni

Technologist  
Niagara College  
Facilities Management Services